




















Ø8x35 6 x K2	Ø6x30 16 x K3	Ø7x50 8 x A1	hex 4 1 x I	Ø15 4 x ZMN
Ø15x12 10 x M1	Ø20 26 x T2	Ø20 16 x ZMN1	Ø6,3x13 16 x W5	Ø3,5x16 1 x W1
6 x G2	4 x D5	1 x Z1	300mm 4 x R6	
Ø3x20 42 x W10	Ø15x10 16 x M2			















A




B


	$\varnothing 8 \times 35$ 4 x T2		$\varnothing 15 \times 12$ 2 x K2		$6 \times M1$
--	-------------------------------------	---	--------------------------------------	---	---------------

**C**

D








Ø15
4 x ZMN

**E****A=B**

F



$\varnothing 3 \times 20$
6 x W10




$\varnothing 3 \times 20$
6 x G2

**G**


$\varnothing 3,5 \times 16$
1 x W1

$\varnothing 3,5 \times 16$
1 x Z1




H**I****J**

K





L



Ø3x20
20 x W10




A=B



M

Ø3x20
16 x W10

300mm



N

