










AXEL III



IF THE WOODEN LEGS ARE LOOSE WITH THE METAL PARTS, PLS DO ABOVE THREE STEPS



A		1
B		1
C		4
D		4
E		4
F		1
G		1